



T- Bird (Hard Top)



- To Fuse Panel 1B1-W
- To BU Light Sw 3BR
- To HL Switch 5B
- To Fuel Gauge 8YW
- To Turn Sig Sw 9-0-B1
- To Turn Sig Sw 10G0
- To Heater Sw 11B0
- To Heater Sw 12-0-Br
- To Dome Lt Ckt 13B-B1

Color Key:
 B - Black R - Red
 B1 - Blue W - White
 C - Green Y - Yellow
 O - Orange

Example: 9-0-B1 Wire #9 Orange with Blue stripe.



Drawn By CDO 12/27/14